

**Romanian Military - Aeronautical Information Publication****AIRAC AIP SUPPLEMENT 01/16****ILS malfunction at LRBO / Boboc Aerodrome****Effective date 03.03.2016**

The ILS radio navigation system is presenting malfunctions. During the reparation period, the following modifications are to be operated:

- RWY 04 authorized conditions of operation: VFR and IFR - NDB, RNAV and PAR only;
- RWY 22 authorized condition of operation: VFR and IFR – RNAV and PAR only;
- Radio navigation and landing aids;

**LRBO AD 2.19 RADIO NAVIGATION AND LANDING AIDS**

<i>Type of aid, CAT of ILS</i>		<i>ID</i>	<i>Frequency</i>	<i>HR</i>	<i>Site of transmitting antenna coordinates</i>	<i>Remarks</i>
LOM 04		BSV	397 KHz	On request	45°09'46"N 026°54'24"E	
LMM 04		BS	332 KHz	On request	45°12'06"N 026°57'32"E	
LMM 04 Nat		BN	507 KHz	On request	45°12'46"N 026°57'14"E	
LLZ 04		IBO	111,70 MHz	On request	45°13'35"N 026°59'32"E	out of service
GP 04		-	333,50 MHz	On request	45°12'34"N 026°58'18"E	out of service
GCA 2000	ASR	-	9025 MHz	On request	45°13'02"N 026°58'39"E	
	PAR	-	9125 MHz	On request	45°13'02"N 026°58'39"E	
	SSR	-	1030MHz/1090 MHz	On request	45°13'02"N 026°58'39"E	

- The following charts are suspended: 2.2-13, 2.2-14, 2.2-15, 2.2-16;
- Estimated period for repair is unknown.

--- END ---